Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	ctor(s): Russo			28-Oct-19
Company/Owner:	y/Owner: Intermountain Gas Company		Unit/OPID:	8160
Inspection Type & Time (1 day) Total Inspection Days: 1				
Inspection Type & Time (1 day) Total In			spection Days:	1
Standard: Construction: 1 Training: (T)(D) Integrity Management: Incident:				
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
28 Oct 2019: (1.0 Construction) Observed a Dasco crew installing a new service with an EFV. They used proper bedding and shading procedures and left a stub and stub marker for the future property next door. Pressure tested the service and tied it in. Typed up report Areas observed during this project were: Excavating, Line locating, Pressure testing, Backfilling				
Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.				
Corrective Action Required:	Follo	ow-up Required: Yes	No No	Х
Yes No	X		by (date):	
Inspector (Lead): Kyle Russo	140	AP-0	Date: 10/28/2019	
Reviewer:	Jak A		Date:	1 Nov 2019